

**Corporate Office** 17522 Bothell Way Northeast Bothell, Washington 98011 425.415.0551 www.riley-group.com

Report No: 133

Project No:

RGI rep: Lizzie Wratten Date:

2019-134

Thursday 3/11/2021

**Permit No:** SW18-00009 Page No. 1 of 1

Project: Mallard Pointe Subject: Subgrade Observations

Southeast 43rd Way and East Lake

Location: Sammamish Parkway Southeast, Issaquah **Contractor:** 

**Client Name:** Steve Burnstead Construction LLC Superintendent

11980 Northeast 24<sup>th</sup> Street, Suite 200 & Address: **Visitors:** 

> Bellevue, WA 98005 Weather: Sunny

## **OBSERVATIONS:**

As requested, a Riley Group representative visited the site today to observe and evaluate the following:

Contractor has excavated to subgrade on Lot 17, 4268 216<sup>th</sup> Place SE, Issaquah, WA. When tested with a 1/2" steel tipped T-probe, the surface yielded less than 1/4" indicating dense conditions suitable for the required bearing pressures.



Contractor has excavated to subgrade on Lot 19, 4256 216<sup>th</sup> Place SE, Issaquah, WA. When tested with a %" steel tipped T-probe, the surface yielded less than %" indicating dense conditions suitable for the required bearing preasures.

RGI Rep sign:	Lízzie Wratten	Copies To:
Reviewed by	Kristina Weller	